

PRODUCT SAFETY NOTICE - WARNING

WINCHESTER 94: PRODUCT SAFETY NOTICE - WARNING

10/ 2/ 2014

WINCHESTER® Model 94 Family of Lever-Action Rifles, Carbines, and Muskets with Half-Cock Safety

Winchester Model 94 (including commemoratives); Winchester Model 1894; Winchester Model 9422 and Model 9422M; Winchester Model 55 Sears® Model 54 and Ted Williams® Model 100; Winchester Model 64 and 64A; Winchester Centennial '66; Winchester Canadian Centennial '67

Olin Corporation, through its Winchester Division, is warning users of the above firearms that when there is a live cartridge in the chamber, **dropping, jarring or bumping the firearm may cause an accidental discharge**, which may result in property damage, serious personal injury or death to the user or others:

With the hammer in the full-down position, a slight impact to, or bumping the hammer can cause a discharge.

With the hammer in the half-cock safety position, a hard impact to the hammer, such as from dropping the firearm, can break the safety mechanism and cause a discharge.

With the hammer in any position, a hard impact, such as from dropping or jarring the firearm, can cause a discharge, even if the hammer is not impacted.

To reduce the risk of accidental discharge, follow safe firearm handling practices, including:

Always maintain control of the firearm and keep your firearm pointed in a safe direction at all times.

Never place the hammer in the full-down position when there is a live cartridge in the chamber. Never rely on the half-cock safety to prevent accidental discharge due to dropping or jarring the firearm, or hard impacts to the hammer.

When there is a live cartridge in the chamber, avoid activities that increase the risk of dropping or jarring the rifle, such as running, climbing, crossing a fence, and taking the firearm up and down from a tree stand.

This is not an ammunition or firearm recall.

For Winchester firearm owner's manuals please go to
www.winchesterguns.com/customerservice/ownersmanuals